



**SOILS OBSERVATION AND TESTING REPORT**

**Site Location:** Monarch Drive, Littleton, MA  
**Project No.:** 5554  
**Date:** 2/21/2023  
**Time of Testing:** 11:00 am

**Weather – Snow**  
**Temp:** 32° F  
**Sky Condition:**

**Notes:**

<u>Deep Hole #</u>	<u>Depth</u>	<u>Soil Texture</u>	<u>Groundwater/Redox.</u>
DH 221-1: (El. 225.2) LARGE BASIN(SOUTH)	0"-65"	SAND	GW WEEPING@42" GW STANDING@63" REDOX@40" (EL. 221.9)
DH 221-2: (El. 225.2) LARGE BASIN(SOUTH)	0"-40"	SAND	GW WEEPING@36" GW STANDING@36" REDOX@34" (EL. 222.4)
DH 221-3: (El. 229.0+/-) SMALL BASIN (NORTH)	0"-24" 24"-99"	FILL SAND	GW WEEPING@99" GW STANDING@99" REDOX@72" (EL. 223.0)
DH 221-4: (El. 228.0+/-) MIDDLE BASIN	0"-80"	SAND	GW WEEPING@77" REDOX@72" (EL. 221.6)